

| No. | Regist | Name | Built | Year O | Year O | Scrapp | Other |
|----------------|-----------|-----------------------------------|---------|--------|--------|--------|---|
| | KD 89-93 | Karosa LC735.20 | 1986 | ? | 2010 | | |
| | 1S3 5813 | Karosa LC735.20 | 1987 | 2008 | 2008 | | |
| | KDA 30-86 | Karosa C734.1340 | 1990 | 1994 | 2006 | 2006 | |
| | 3P3 8394 | Oasa 901 HD 12 | 1992 | 2001 | 2007 | 2012 | 1992 - 1995 Lema, Praha |
| | 3H6 3042 | Karosa B732.1658 | 1994 | 2004 | 2007 | | pro potřeby autoškoly DP Hradec Králové |
| | 9S8 2210 | Karosa C734.1340 | 1994 | 2010 | 2011 | 2011 | |
| | 6S6 7929 | Karosa C934.1351 | 1997 | 2008 | 2013 | 2014 | 2013 -> 2014 Jiří Zíka, Brandýsek |
| | 6S6 7919 | Karosa C934.1351 | 1997 | 2008 | 2014 | 2014 | |
| 1 2 5 1 | 4SA 6298 | Mercedes-Benz O560-15RH | 1999 | 2007 | | | |
| | 1BS 6427 | Karosa LC936XE.1038 | 2001 | 2011 | 2017 | | 2017 -> Renata Ondrášková - CA KARREN |
| | 8U2 7210 | Karosa LC956.1072 | 2001 | 2005 | 2016 | | 2016 -> BUDOS-BUS |
| | KLO 55-56 | Karosa C954.1360 | 2001 | 2001 | 2016 | 2016 | |
| 1 2 5 2 | 3SB 8879 | Karosa C955.1073 | 2002 | 2014 | | | |
| 1 2 5 3 | 3SY 1507 | Karosa C954.1360 | 2002 | 2016 | | | |
| 1 2 5 3 | 2S9 2037 | Karosa C954E.1360 | 2003 | 2019 | | | |
| 1 2 5 4 | 3B5 4537 | Karosa C954E.1360 | 2005 | 2017 | | | |
| 1 2 6 1 | 4SA 7848 | Volvo 8500LE 6x2 | 2007 | 2017 | | | |
| | 3SY 8565 | Irisbus Evadys HD 12.8M | 2008 | 2016 | | | |
| 1 2 5 6 | 4SB 9818 | Iveco Crossway 14.5 LE | 2012 | 2017 | | | |
| 1 2 5 8 | 4SK 0906 | Scania CK280UB 4x2 LB Citywide LE | 2007ban | 2017 | | | |
| 1 2 5 7 | 4SA 9099 | Iveco Crossway 12 LE | 2017 | 2018 | | | Crossway LE Line 12M □ □ EZ 01/2018 |