

No.	Regist	Name	Built	Year O	Year O	Scrapp	Other
	HB 85-83	Karosa C734.00	1981	1990	1996	2005	
	KVA 80-12	Ikarus 280.08	1983	1983	1996	2003	
	CVA 46-00	Karosa C734.00	1985	1985	?	2008	Autobus určen pro provoz na linkách MHD v Klášterci nad Ohří
	CVA 33-10	Liaz 101.860	1987	1993	1996		2009 - reko in Czech Camion Servis Milevsko
4 5	CV 93-53	Karosa B732.20	1987	1987	1996	1999	
9 6		Karosa B732.20	1987	1987	1996	2006	
4 7	CV 98-08	Karosa B731.20	1988	1988	1996	1999	
3 2	CV 98-07	Karosa B731.20	1988	1988	1996	1999	
1 7	CV 98-06	Karosa B731.20	1988	1988	1996	1999	
	CV 95-24	Karosa C734.20	1988	1988	1996	2003	
	CV 95-63	Karosa C734.24	1988	1988	1996	2008	Reko v DPCHJ
	CV 94-82	Karosa C734.20	1988	1988	1996	2004	
	CV 94-81	Karosa C734.20	1988	1988	1996	2002	
	6S2 3434	Karosa C734.20	1988	1988	1990	2011	
3 9	CV 98-09	Karosa B731.20	1988	1988	1996	1999	
5 3	CVA 02-31	Karosa B731.40	1989	1989	1996	2000	
	CVA 02-39	Karosa B731.40	1989	1989	1996	2000	
1 5	CVA 02-38	Karosa B731.40	1989	1989	1996	1999	
3 4	CVA 02-59	Karosa B731.40	1989	1989	1996	2009	reko na B732
8	1U0 3237	Karosa B731.40	1989	1989	1996		B731.40 » B732.40
7	CVA 02-36	Karosa B731.40	1989	1989	1996	2002	
	CVA 03-00	Ikarus 280.08	1989	1989	1990	2000	
	CVA 04-67	Ikarus 280.08	1989	1989	1990	2003	
	CVA 05-95	Karosa LC735.1011	1989	1989	1996	2004	
	CVA 00-88	Karosa LC735.40	1989	1989	1996	2001	
	CVJ 31-75	Karosa B731.40	1989	1989	1996	2009	Reko na B732 u DPCHJ
1 2	CVA 02-37	Karosa B731.40	1989	1989	1996	2000	
	CVA 09-57	Karosa C744.24	1990	1990	1996	2001	
	CVA 09-58	Karosa C744.24	1990	1990	1996	2005	2001 - GO Zliner Zlín □ □ 2002 - přesun na MHD
	CVA 10-11	Karosa LC735.1011	1990	1990	1996	2007	
	CVA 04-68	Ikarus 280.08	1990	1990	2001	2003	
	CVA 13-32	Karosa C744.24	1991	1991	1996	2004	
	1U0 3248	Karosa B741.1908	1991	1991	1996	2012	
	CVA 15-14	Karosa C734.1340	1992	1992	1996	2006	